

2730258 ONTARIO LTD. o/a
BRYAN'S SEPTIC SERVICE
P.O. BOX 37
WESTPORT, ONTARIO
K0G 1X0
(613) 277-3333
bryansseptic@hotmail.com

PUMPER REPORT
SEPTIC SYSTEM MAINTENANCE
& PUMPING INFORMATION

Name: [REDACTED] Date: June 27, 2024
Phone: _____

Address: L12 #161

Location: FARROW Lake

Type of Tank One Compartment Two Compartment
Type of Tank Septic Tank Graywater Aerobic Other _____

Approximate Capacity 600 gal

Construction Materials Concrete Steel Block Fiberglass Plastic
 Other _____

Initial Inspection

Any part of the septic tank under deck, driveway, etc Yes No

Any evidence of sewage seeping from the tank or lid Yes No

Condition of top and lids Good Leaking Needs Repair

Before Pumping

Condition of sewage in tank NORMAL

Liquid level at the outlet invert Above Below Normal

After Pumping

Condition of inlet baffle Good Needs Repair Missing

Condition of outlet baffle Good Needs Repair Missing Filter

Evidence of water leakage: Into Tank Yes No From Tank Yes No

Absorption System

Type of Absorption System Seepage Bed Sand Mound Sub-surface Sand Filter

Flow Test Yes No Approximate Seepage at Bed 30 min good

Comments

At time of pumping system in good
WORKING condition

Bay