

2012 Shibley Road, Sharbot Lake, ON

#	40668140
\$	\$1,275,000
	3 Bedrooms
	2 Bathrooms
К Л	1.4 Acres
>	Sharbot Lake

Sitting on the shores of Sharbot Lake and nestled in the trees stands this superbly crafted Normerica Timber Frame Home.

As you come up the driveway, a relaxing feeling comes over you and you realize you are experiencing something special. Upon entering the home, the build quality is evident and that feeling continues. The main central area of the home is timber frame construction and the balance of the home is traditionally constructed. The main floor has a large living room with soaring cathedral ceilings, a wood burning fireplace and is open to the dining area and beautiful custom kitchen. From the kitchen you can head out to the bright 3-season sunroom and onto the multi-level composite deck.

Your Total Real Estate Package!

Tammy & Heath GurrRoyal LePage ProAlliance Realty, Brokerage

info@gurreathomes.com



(613) 273-9595

Not intended to solicit clients under contract. The trademarks REALTOR®, REALTOR® and the REALTOR® logo are controlled by The Canadian Real Estate Association (CREA) and identify real estate professionals who are members of CREA. Used under license. The trademarks MLS®, Multiple Listing Service® and the associated logos are owned by The Canadian Real Estate Association (CREA) and identify the quality of services provided by real estate professionals who are members of CREA. Used under license.

Table of Contents

2012 Shibley Road Sharbot Lake, ON



Features	3
More Information	4
Floor Plan	5
Survey & Aerial Images	8
Well Record	9
Water Test	10
Septic Documents	11
Interactive Links	14
MLS Listing	15
Contact Information	16



Features

- Sitting on the shores of Sharbot Lake and nestled in the trees stands this superbly crafted Normerica Timber Frame Home.
- As you come up the driveway, a relaxing feeling comes over you and you realize you are experiencing something special.
- Upon entering the home, the build quality is evident and that feeling continues. The main central area of the home is timber frame construction and the balance of the home is traditionally constructed.
- The main floor has a large living room with soaring cathedral ceilings, a wood burning fireplace and is open to the dining area and beautiful custom kitchen. From the kitchen you can head out to the bright 3-season sunroom and onto the multi-level composite deck.
- Back inside you will find a main floor primary bedroom and a stunning 4pc. main bathroom. Up the timber frame stairs to the loft area there is an open area currently being used for another bedroom with views down over the living room and out through the windows down the stone stairs to the lake.
- On the basement level you will find another bedroom, a 3pc bathroom, a recreation room and a large room used for laundry, utility and workshop. The lower level has access out to the yard and down to the lake.
- As you meander down the stone stairs the view opens up to a large stone patio, fire pit, pergola, dock and deep clean waterfront. Facing mainly west means you will have glorious sunsets while enjoying time with family and friends around the campfire.
- The home is serviced by a drilled well with UV filtration, septic system, on-demand propane boiler, in-floor radiant heat and has an air handler to bring the heat to the upper levels and allow for the easy addition of AC.
- Stunning property in every way and located just 12 minutes from the village of Sharbot Lake on a year round road.

Directions

• Hwy. 38 south of Sharbot Lake to Shibley Road. Follow to end to #2012.

MORE INFORMATION

Noramerica Timberframe Home 2000

A beautifully crafted timber-frame home featuring 2 bedrooms, 2 bathrooms, and a loft. This lakeside retreat offers a blend of modern comforts and rustic charm.

Key Features:

- Living Spaces:
 - Great Room: Timber-frame construction with vaulted ceilings in the master bedroom, kitchen, dining area, and main bath.
 - Screened Porch: Insulated floors, walls, and roof with Wonder Wall windows and screens.
 - Basement: Lakeside wall framed, 3-sided poured concrete foundation on granite.
- Outdoor Amenities:
 - Deck & Patio: 2-tier composite deck with bistro bump-out, mixed picket rail, and glass. 2-tier patio at the lakefront with a pergola.
 - Dock: 3-section dock with a swim ladder, boat bumpers, and cleats.
 - Pathways: Complete path around the house leading to the lakefront.

Utilities & Systems:

- **Water Supply:** Well with 6 GPM output, full UV filtration, water softener, reverse osmosis in the kitchen, and an external hose tap.
- **Electrical:** 200 amp service, driveway post light, and power receptacle at the waterfront pergola. Fibre optic Wi-Fi system installed.
- **Heating & Cooling:** Propane-based heating, closed in-floor system in the walkout basement, forced air on the main and loft floors, ducting ready for A/C, and an Ecobee Wi-Fi thermostat.
- Septic System: Gravity septic with an 800-gallon tank and room for an additional bathroom.

Insulation & Build Quality:

- Great Room Roof: R35 solid foam insulation.
- Vaulted Ceilings: R49 battens in the wings.
- Exterior Walls: R24 solid foam insulation.
- 25-Year Roof Shingles


Additional Features:

- Tech & Security: August Lock Wi-Fi front door lock system.
- HRV System: Replaced in 2022.
- **Chattels Included:** Adirondack chairs, lakeside patio table and chairs, BBQ, dining table with chairs, and porch lighting.




This information is believed to be accurate but is not warranted. Buyers to verify accuracy of all information.

FLOOR PLAN 1/3



FLOOR PLAN 2/3



FLOOR PLAN 3/3




FLOOR 3

GROSS INTERNAL AREA FLOOR 1: 914 sq.ft, FLOOR 2: 1173 sq.ft, FLOOR 3: 239 sq.ft EXCLUDED AREA: DECK: 534 sq.ft, PORCH: 391 sq.ft TOTAL: 2326 sq.ft

SIZES AND DIMENSIONS ARE APPROXIMATE, ACTUAL MAY VARY.

SURVEY






WELL RECORD

11.22


Quesale anno a		Address				Date	
Frontenac	1.114 (2.44 (44))	050	NAR SERVICES AN 1	a	2	C) - Cordia	8
County or District	414 581 40	Township/Borough/	City/Town/Village	FLOREW EXT	Con block	tract survey, etc.	Lot
	51 - CAG 🔾	HI HETAR FORER		101 - 3° 27		199.8 - 403	4
		THE ALL ALL	A BANK DI LIBORI DU VILL		11	the star price	
ark correct box with a checkmark.	where applicable.	Control Walson	and shares and	Antonio secono d	NO 1 STAR	1. 30	
rint only in spaces provided.		a the				1	5.5205261
id Energy الشنانغري	(2) ± 17	TO VELL STRERS	RL OF INTERT	1.37 1.08	RETAVOIRES		ECONI
, tronment	1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 -	14.08008 000 100	CARGESS AND	<u>1 </u>		WELL R	
101 OT	We are	TANEOR PHA TOA	A DECKERSING A	u bisana se t	he Ontario	Water Reso	urces /
50							

e the set if A 21 AVB0 THERE I A ST TA SEC APA CONTRACT OF

General colour	Most common material	Other materials	General description	and the second second second	pth - feet
	territe data and the second se		14	From	To
	boulders	1776 - 1794 СТ ТАНТ 1736 - сторо с те 1776 - 1716 - СТАК ТАРАТУГ	and the second	0	9
red	granite		black	9	256
		BANDLANCKY, REFERENCE SACKED IN			
			a go transfer and the		
		CHOILANA JAKA	<u> </u>		
<i>C</i> 13	e u spande		$\sum_{i=1}^{n-1} \left[1 - i \right] = \sum_{i=1}^{n-1} \left\{ A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{1}{2} \frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{1}{2} \frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{1}{2} \frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{1}{2} \frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{1}{2} \frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{1}{2} \frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{1}{2} \frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \right] A^{(i)} (i + \gamma - i) e^{i - \frac{1}{2} \left[\frac{N}{N} (O X) \left[\frac{N}{N} (O X) \right] A$		21
	3	. FALLE THE SHE SHE OF OSTELNED.	10000000000000000000000000000000000000	1.	*. .
		1	 Constraint Statements (1994) 	12002-	0
		122	Shi Abi Shi 1400 di kilar Sadha 1926) ali - Shi 112 an Adri		
	8.10		T BRST DESCRIPTION TO THE PART OF THE P		



WATER TEST



Public Health Laboratory - Kingston 181 Barrie St KINGSTON, ON K7L 3K2

Bacteriological Analysis of Drinking Water for Private Citizen, Single Household Only Ana

Submitter's Name and Mailing Address /	Location of Water Source /
Nom et adresse postale de l'auteur de la demande d'analyse	Emplacement de la source d'eau
First Name, Lasi Name / Prénom, Nom de familie	Lot, Concession / ou lot, concession Emergency Locator # / 011#
HEATHER GURR	2012
Strant address / Adresse municipale	Street address / Adresse municipala
7 SPRING STREET	2012 SHIBLEY RD
WESTPORT, ON KOG 1X0	CENTRAL FRONTENAC ON K0H2B0
	County / Comid: FRONTENAC
	Health Unit # / # du bureau de sanié: 2241

Specimen details / Détails sur l'échantilion:

Barcode / Code à barres: 012831295 Phone # / # tél.: 613 985 2414

Date/Time Collected / Date/heure du prélèvement*: 2024-10-21 17:00:00

Date/Time Received / Date/houre Recu le*: 2024-10-22 11:44:00

Purification system used (e.g. UV, filtration, etc.)? / Système d'épuration utilisé (p. ex. rayons UV, filtration, etc.)?

Yes / Oul

Authorized by / Autorisé par

Chief, Medical Microbiology or Designate

Specimen Note / Note sur l'échantillon:

This specimen was received in good condition unless otherwise stated./A moins d'avis contraire, l'échantillon était en bonne condition au moment de la réception.

Test results / Résultats d'analyse:

Total Coliform CFL	100 mL / Coliformes totaux UFC/100 m	L 0
E.coli CFU/100 mL	E. coll UFC/100 mL	0
Interpretation / Inte	orétation:	
There is no evidence	of fecal contamination. If the results sho	w the presence of coliforms it may be
indicative of a contr	ninated water supply. Given the suscept	ibility of well water to external influences, it
	ater frequently. Consult local health unit	
		ts indiquent la présence de coliformes, cela
peut être révélateur	d'une source d'eau polluée. L'eau des pu	its étant susceptible d'être dégradée par
des facteurs extern	s, il est important de la faire analyser frér	quemment. Consultez le bureau local de
	plus de détails, si nécessaire.	
Date of Analysis / Date	e l'analyse: 2024-10-22	Date Read / Analyse effectuée le: 2024-10-23

Please Note / Prière de noter ce qui suit :

The results apply to the sample as received/Les résultats s'appliquent à l'échantillon, tel que reçu.

These results relate only to the sample tested. I Le résults a apporte seulement à cet échantilion d'eau analysé. Note : This water sample was only tested for the presence of both Total Collignms and E. coll (ISO/IEC 17025 accredited tests) bacterial indicators of contamination by Membrane Filtration. The sample was not tested for other contaminants, including chemical contaminants, and therefore may be unsafe to drink even when there is no significant evidence of bacterial contamination. Contact your local public health unit for information on testing for other contaminants / Remarque: Cet échantillon d'eau n'a été analysé que pour déceler (par un laboratoire accrédité conformément à la norme ISO/IEC 17025) la présence des coliformes totaux et des bactéries collibacillaires, indicateurs de contamination par filtration sur membrane. L'échantillon n'a pas été testé pour d'autres contaminants, y compris les contaminants chimiques et, par conséquent, l'eau peut être impropre à la consommation même lorsqu'il n'y a aucune preuve significative de contamination bactérienne. Veuillez communiquer avec le bureau de santé publique de votre localité pour vous renseigner au sujet de l'analyse visant à détecter la présence d'autres contaminants.

If the reported client information does not match the information you supplied on the form please contact the PHO Customer Service Centre. Telephone: 1-877-604-4567 or 416-235-6556 or E-mail: customerservicecentre@oahpp.ca. For operating hours see our website www.publichealthontario.ca/labs. / Si les informations sur le client indiquées ne correspondent pas aux informations que vous avez fournies sur le formulaire, veuillez communiquer avec le Service à la clientèle de SPO par téléphone au 1-877-604-4567 ou 416-235-6556, ou par courriel au customerservicecentre@oahpp.ca. Pour connaître les heures d'ouverture, veuillez consulter notre site Web à www.publichealthontario.ca/labs

End of report / Fin du rapport

*All time values are EST /EDT/Toutes les heures sont exprimées en HNE ou en HAE.

	THE REAL PROPERTY AND ADDRESS OF THE REAL PROPERTY	
Print Date / Date d'impression*: 2024-10-23	Page 1 of 1	LIMS Report #: 54108116 Dontario
Date Reported Date du rapport*: 2024-10-23 15:35:53		T_SingleSampleOPHL_WATPRIVATE.pt

SEPTIC DOCUMENTS

KINGSTON, F	RONTENAC AND LENN	OX &	ADDI	NGT	ON	HEA	LTH	UN	IT				1000	AP	PLIC	ATI	ONI	NO.	н	ł.U.G
221 PORT	SMOUTH AVENUE, KINGSTO NG, DUNDAS ST.W., NAPANE	N, ONT	ARIO	CLO SHA	YNE, RBOT		ARIO (E, C	NTA	RIO				1	0	5	-1	5	- 9	7 E	bbi
	NAL INSPECTION FOR CLAS	S 4, 5 5	SEWAG	GE SY	STEN	٨		33		3 1. 7				1000 - 10000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1000 - 1	da da	2.5.1			U	1
SPECTION DETAILS	<u> </u>				\sim	_				11	100					210				
IME 8:30 A.M. DATE	Oct 4, 1999 0	WNER	/						NST	TALL	ER	Gr	ay	18	ras	r. (Con	<u>st.</u>	L	td
Work has been satisfactorily		- 19 17 - 19	~							jî,					1	911				
a) Septic tank/holding-tank	of working capacity of							of st	eel C		oncr	ete i	a fi	berg	glas	sū	plas	stic C	1	
on site i or prefabricat	ed □ to serve <u>3</u> PREFABRICATED TANK <u>A</u>		of be	droom	s or u	inits).							9	ζ.		0				
 b) Leaching/Filter Bed of to 	otal @20 273 metres of	3	inch di	amete	r dist	ributic	on nin	e of	R	2/1	~/	1.	<u></u>	(1)	/ne	and	pro	duct	des	crip
laid inruns a	nd fed by Grauity (gravity	y, siphor	, pum	p). If F	ilter E	Bed, L	.oadir	ig an	eal	a'x.	24	12	6.5	EM2	Cor	ntaci	t Are	a	000	onb
c) Secondary or Tertiary Tr				_				(Mo						_						
d) Other details																	-			
Location	4.1. X. I.	desired or	and.		1.54	6.13.		.1.3		2242	a.e. b		2.5	1.36	83.5	in a	A 127			
	talled as shown on application a) use space below for sketch															tate	futt	ire lo	ocatio	on c
	cluding orientation of pipe run			1									17		*		1			
				1			1	1.		10	5	100	120		10.5	5.4	1	T		
		La	Ke	10		100					靈	100	in the		14			1	191	1
			T	3.		34	š. 1.	12.		14			13		26.1	4	1			
				1		1.1	12				E.		1			1			1	2
							11	1.5		1.1.1	0.2	10	4	1	1.5	-			-	2
		1.20			2.54		-	1	1	1.0			1	100	151	100	-	-	-	
				35			r.	1.1		194	2. 1		1	4.75	100	14	-	-	-	2
			100	-		1	A			Sec.	10-14 10-14	1	1	100	1282	36	120			-
		11	100	*		The sea	1	100		10		1.54	13		12		1.00	-		
				14		1.			ang.	1			1		E.	35				
				11	12.0	いなど	1	12,44	1.0		12		CH I	en.	100	100	1	·		
		E IT	¥	1995	12.			35	20	25.1		100		1		2.	1.0			
		1.10		-		-	2		_	~	20	2.4	3	1.46	1	-	-		_	
		84 24	5	333	in the second	23- 54 615 5	1 2 12 IL	1000	Tar Tar	-30	1	-42	0.55	NU.	120	化合	2.3	34	-	1
		2	1 th	-201	124	F 19.4	416'3	-	20		5,67 5,11	28	· 影	教育	1.5	<u>G 9</u>	1.5		-	
			-	-	and 1	avel		1	-	-	1.1		100		<u>1</u>		1	hi	-	
			1	14	1º	2	1	-		Ť	-			453	1					
			6	44				11		22		-								
				110	1911	1				3	1	2	1							
		14		J										14	12					
	4.92 2019	1		10 L	lell	100				1			and a					-		
		-	N	-			1	3			1	-			1		12		1	_
		100	2				12.3	-	-	-	-		3	122			-	-	-	
		1 S	105		10 m 1	14	1	-	-	-		7 8	120	120		2.		-	-	-
			XIT	•••	1.0	- 13. 1993 - 14		1		-	1	125		12	185	1.1	2			
			140	100		10	200	10	1		3	3		1	1		-			1
		10	12		1		10.11	1.1		27	3	1		11.2				-		
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			Ym		18.12	1.00	-	5	10	31	3	-0-	2.2		4		-		-
		144 C 1 X 2	CPCO PA	31 8125	1.1.1.1	1 35.2	(1) 2, 100	1000	N 1	1012	S. 10	2.42	22312	10.1	12.2	10.0	1.11			

SEPTIC DOCUMENTS (INSPECTION 2023)

storringseptic@ H.S.T. # 84875 6	hotmail.com 1078 RT0001		
INVOICE No. 45026	Date Oct.	7	202
Address 2012 Stibley Rd	Sharbot	Lt.	
Holding Tank		AMOUN	m
Septic System	8000	315	00
A STAR MARTIN AND A STAR AND A STAR AND A STAR		21-	
Labour Cleaned Filte Notes cleared roots int at top of tout.			
Notes cleared forts int			
Notes cleared forts int			
Notes cleared costs int at top of touts.	ruding	-	0
Notes cleared costs int at top of touk.	Cican Fitter Regularly	315	0

SEPTIC DOCUMENTS (INSPECTION 2013)

A REAL AND ALL IN THE REAL AND A R	deau Sy		pection I	Type	
Locieuri 7 11 5	- 6 Day 2		015 113	A second s	
Assessment Aut #	a buy here	1	Permit #	Age of System	4
kill.	DAG HAN 2-	100	a respect to the second s	Lasto Shullet	
Property Owner	ALLY .		Compe Checker		1279
Manung Address 7-5	No mar her				
Cer 1 Dis	Potenti Konin	711 221	Questionnary Relations	a prima prime	and the
System 6			Owner Present Cl pt	10159 E	
	and a of Bester	ama	Est. Design Flow	-	Liday
Explanated Design Flow Plott A		and the second second	same in particul same f	Like 🗇 monited 🗇	Caramon
Mater Source Pipe from Hammwelth Source.		Crime	Citria concer	n Chesposed Chespo	er inquired
System Class 1 (Days 1 (Days Co	repositing Tales Of Char	2 FOW PER CO Class	a d'ansi aa	Lasti S	
	3	Concrete Challen	Christie Christer	gima	
Composing toller CT yes	AN I COMPANY AND A REAL PROPERTY OF			M + approxM*	· 0
Overflow (7) yes Structure (7) good		ng Ovenber Dige pitevel Alarmi (Dige		user Cityes	
Menting (7 good	T required Eth		d recommended	CLEARE CO YES	Chine
Claiming Claimin 2	C repair required		1		ri same
Permit Available 🗇 ym 🗄	no C	other public .	11		
Crepwater to surface (7) yes (Approximate size	3 mb	di mar	i and	T De	equired
Approximitie depth of so-		and a second sec	1 NUM (M]	and locally	Colores and
Construction		the second se	i skatje	and an	
treatment Unit Manufacturer Mod			Marcenarice	Agreement 🛈 yes	13 ma.
Distribution System	Clearance Distan Tark to water		Sheet by Landson	an la	
C trench C Filter Media	lack to well	17 m	Pipe to water	70 m	-
C Area Bed C Unknown	Tarik to house	15 11	Pipe to house	21 -	12
Side slopes scattle II yes I nd	Tank bo line	3	Pipe to line	73 m	110
trolion concerns 17 yes 13 no. Soft spongy ground 13 yes. 13 no.	Privy to water Poly to line		U.W. to tere	m	-
Efficentiat surface Diver Dina	PTINY TO WER	m	G W to well	- m	2
Amount of cover		m			12
GPS No Signal Cl	Lale Per	Th Ch and	TENTE	2015	=
ank N 11 32441 TE 4 93	and the second s	CN CN	IE IE	L'al	- 17
not in pack and a lite 1993		EN SELEL	I TE AYES	-	- 16
Valuet Status	Remodal Work Restard	-			-
NO CONCERNS	CI PLMP OUT RECURE		Re-Inspection Reg	areat by:	16
REMEDIAL WORK PEOPLER	P MONITOR CONSIDER		CT SITTE VISIT #2		- 11-
SYSTEM REPLACEMENT REQUIRED	S RE-INSPECTION NEO		D ORDER TO COM	PLY	
And and an and a second			D WORK COMPLET	no.	- 2
MORE THE ORMATION REQUIRED					- 0
MORE TWO ORMATION REQUIRED	he from had	A had a	aptr at		and the second se
MORE INFORMATION REQUIRED	In her hall	R han p	empeat		
MORE TWO ORMATION REQUIRED	a for hel	R Site P	anyout atua	21200	- 4
MOR WORMADON REQUIRED	the first had	E hay b	ation as b	2 Fryd	- 4

INTERACTIVE LINKS

Virtual Tour





Scan the QR Code or Visit: https://my.matterport.com/show/? m=CcrFfQkc5Uw

Google Map





Scan the QR Code or Visit: https://maps.app.goo.gl/ T4nZTMBVKNHhp4oo7

Video Tour





Scan the QR Code or Visit: https://youtu.be/cXiRQ7L-FPE

Panorama View





Scan the QR Code or Visit: https://360panos.org/ panos/2012Shibley/

MLS LISTING

2010 SHURLEY Dood Charbet Lake Optaria KOLLODO

lient Full	esiden	tial	2012 SHIBLEY R	d Sharbot Lake	2		J ID: 40668140 ce: \$1,275,000
			1.5 Store	nac/Frontenac/ y/House dy: Sharbot Lake ater: Lake	45 - Frontena	ic Centre	
			Basement Main Second	Beds Baths	Kitch Beds (AG Baths (F-4 SF Fin To AG Fin SF AG Fin SF BG Fin SF BG Fin SF	H): tal: Range:	3 (2 + 1) 2 (2 + 0) 2,326 1001 to 1500 1,412/Plans 914/Plans 0
	1				Common Tax Amt/		Freehold/None \$5,192.99/2024
	Frame experies continu- traditio burning out to t floor pr an oper the win bathroo access large st gloriou drilled	Home. As you com encing something s uses. The main centu- nally constructed. g fireplace and is o the bright 3-seasor rimary bedroom an n area currently be ndows down the sto om, a recreation ro out to the yard ann tone patio, fire pit, s sunsets while en well with UV filtrai	Remark harbot Lake and nest e up the driveway, a special. Upon enterin ral area of the home The main floor has a open to the dining are n sun-room and onto id a stunning 4pc ma sing used for another one stairs to the lake opm and a large room d down to the lake. A pergola, dock and d joying time with fam tion, septic system, o	relaxing feeling or g the home, the bu is timber frame co a large living room as and beautiful ou the multi-level co in bathroom. Up th bedroom with vie bedroom with vie c. On the basement a used for laundry, us you meander do eep clean waterfro hily and friends arcon- demand propan	omes over you a uild quality is evi mstruction and t with soaring cat istom kitchen. Fi mposite deck. Bi he timber frame ws down over th t level you will fi utility and work t level you will fi utility and work sont. Facing main bund the campfir ie boiler, in-floor	nd you rea dent and t he balance thedral cei com the kit ack inside stairs to th el living ro nd anothe cshop. The airs the vie ly west me e. The hon radiant he	lize you are hat feeling of the home is lings, a wood chen you can head you will find a main te loft area there is iom and out throug r bedroom, a 3pc lower level has wo opens up to a ans you will have he is serviced by a sat and has an air
3	way an	d located just 12 n	ninutes from the villa : Lake to Shibley Roa	age of Sharbot Lak	e on a year roun		
- to do at T -		Discret Westerdame		aterfront	Direct Water V		
aterfront Typ aterfront Fea ock Type: noreline: nore Rd Allow nannel Name	atures:	Direct Waterfront Water Access Dee Private Docking Clean, Deep, Rock Owned	eded	Water View: Boat House: Frontage: Exposure: Island Y/N:	155.00 West No	lew	
	15		E	Exterior		and An Percent	
terior Feat: instruct. Mat ingles Repla ar/Desc/Sou operty Acces her Structur	iced: irce: is:	Deck(s), Fishing, Board & Batten, S 2000 2000//Owner Municipal Road	Landscaped, Patio(s) Folid Brick Foundation:), Porch-Enclosed, Poured Concret	Roof:	ed:) Asphalt Shingle Detached 16-30 Years Fully Winterized
arage & Parki irking Spaces ervices:		6	ble Wide//Gravel Driv Driveway Spaces: tricity, Fibre Optics, F	6.0	Garage Spa et, Telephone Av		
ater Source:		Drilled Well 1.400/Acres	Water Tmnt: Acres Range:	UV System, Wa Softener 0.50-1.99		P. P	Septic, Septic Approved
t Size Area/I		155.00	Lot Depth (Ft):	503.00	Lot Shape:		Irregular
ot Front (Ft): ocation:			Lot Irregularities: Beach, Campground, Is, Shopping Nearby,		Land Lse Fe Island, Marina, F		of Worship, Schoo
ot Front (Ft); ocation: rea Influence lew:		Access to Water, Bus Route, Schoo Forest, Lake, Tree	Lot Irregularities: Beach, Campground, Is, Shopping Nearby, es/Woods, Water		Island, Marina, F Retire Com:	Park, Place	
ot Front (Ft): cation: rea Influence ew: pography:		Access to Water, Bus Route, Schoo Forest, Lake, Tree	Lot Irregularities: Beach, Campground, Is, Shopping Nearby, ss/Woods, Water ng, Wooded/Treed	Trails, Other	Island, Marina, P	Park, Place	of Worship, School West West
bt Front (Ft): cocation: rea Influence iew: opography: estrictions: 	Air E Softe Carb Full I t: Walk In Ba	Access to Water, I Bus Route, Schoo Forest, Lake, Tree Hilly, Rocky, Rolli xchanger, Ceiling I mer, Workshop on Monoxide Detec Basement (-Out asement, Lower Le	Lot Irregularities: Beach, Campground, Is, Shopping Nearby, ss/Woods, Water ng, Wooded/Treed Fans, On Demand Wa ctor(s), Smoke Detec Basement Fin:	Trails, Other nterior ter Heater, Ventila	Island, Marina, F Retire Com: Fronting On Exposure:	Park, Place	West West
ot Front (Ft): ocation: rea Influence lew: bopography: estrictions: 	Air E Softe Carb Full I t: Walk In Ba None Firep 1/Lis Built Wast : Wast	Access to Water, Bus Route, Schoo Forest, Lake, Tree Hilly, Rocky, Rolli xchanger, Ceiling I aner, Workshop on Monoxide Detec Basement -Out asement, Lower Le cout asement, Lower Le cout ane Tank -in Microwave, Car her, Window Cover her "As Is", WiFib	Lot Irregularities: Beach, Campground, Is, Shopping Nearby, ss/Woods, Water ng, Wooded/Treed I Fans, On Demand Wa ctor(s), Smoke Detec Basement Fin: vel ropane, In-Floor, Rad	Trails, Other nterior ater Heater, Ventila ater(s) Fully Finished diant, Wood tor, Dishwasher, D m TV and Mount, L	Island, Marina, F Retire Com: Fronting On Exposure: ation System, Wi FP Stove Contract Dryer, Refrigerat	Park, Place : ater Heate Op: Cost/Mo: or, Smoke 1 Sunroom	West r Owned, Water Yes Detector, Stove, , BBQ, Patio Tables
bt Front (Ft): occation: rea Influence iew: oppography: estrictions: 	Air E Softe Carb Full B Tull B None Firep 1/Liv t: Prop Built Wash : Wash and C	Access to Water, Bus Route, Schoo Forest, Lake, Tree Hilly, Rocky, Rolli xchanger, Ceiling I aner, Workshop on Monoxide Detec Basement -Out asement, Lower Le cout asement, Lower Le cout ane Tank -in Microwave, Car her, Window Cover her "As Is", WiFib	Lot Irregularities: Beach, Campground, Is, Shopping Nearby, ss/Woods, Water ng, Wooded/Treed I Fans, On Demand Wa ctor(s), Smoke Detec Basement Fin: vel ropane, In-Floor, Rad	Trails, Other nterior ater Heater, Ventila ater(s) Fully Finished diant, Wood tor, Dishwasher, D m TV and Mount, L	Island, Marina, F Retire Com: Fronting On Exposure: ation System, Wi FP Stove Contract Dryer, Refrigerat	Park, Place : ater Heate Cost/Mo: or, Smoke n Sunroom Naterfront	West r Owned, Water Yes Detector, Stove, , BBQ, Patio Tables
bt Front (Ft): breation: real Influence iew: oppography: estrictions: interior Feat: ecurity Feat: asement: asement Feat sundry Feat: ooling: eating: replace: nder Contracticusions: dd Inclusions lectric Age: umace Age:	Air E Softe Carb Full I t: Walk In Ba None Firep 1/Liv t: Prop- Built Wast and (chair 24 2	Access to Water, Bus Route, Schoo Forest, Lake, Tree Hilly, Rocky, Rolli xchanger, Ceiling I aner, Workshop on Monoxide Detec Basement -Out asement, Lower Le lace, Forced Air-Pr ving Room, Wood ane Tank -in Microwave, Car her, Window Cover her "As Is", WiFi D 6 Chairs, Dock, All 's under Pergola	Lot Irregularities: Beach, Campground, Is, Shopping Nearby, ss/Woods, Water ng, Wooded/Treed I Fans, On Demand Wa ctor(s), Smoke Detec Basement Fin: vel ropane, In-Floor, Rad bon Monoxide Detec ings oor Lock, Living Rooi waterfront patio woo Plumbing Age: Tank Age:	nterior iter Heater, Ventila iter (s) Fully Finished diant, Wood tor, Dishwasher, D m TV and Mount, L od & composite Ad 24 10 y Information —	Island, Marina, F Retire Com: Fronting On Exposure: ation System, Wa FP Stove Contract Dryer, Refrigerat ights and Vine in irondak chairs, V Furnishe UFFI:	Park, Place : ater Heate Op: Cost/Mo: or, Smoke n Sunroom Naterfront d:	West r Owned, Water Yes Detector, Stove, , BBQ, Patio Tables
ot Size Area/L ot Front (Ft): ocation: rea Influence fiew: bopography: lestrictions: interior Feat: lasement: lasement: lasement: lasement Feat lander Contract inclusions: leating: ireplace: Inder Contract inclusions: dd Inclusions lectric Age: umace Age: inder Contract nclusions: lectric Age: umace Age: inder Contract nclusions lectric Age: inder Contract nclusions lectric Age: inder Contract nclusions lectric Age: inder Contract nclusions lectric Age: inder Contract inder Contra	S: Air E Softe Carb Fuil I Fuil I Fuil I None Firep J/Li Y Suilt Wash and (chair 24 2 Fee: N Free Free PT RW Z Softe Suilt Suilt Suilt Suit Suit Suit Suit Suit Suit Suit Sui	Access to Water, Bus Route, Schoo Forest, Lake, Tree Hilly, Rocky, Rolli xchanger, Ceiling I ener, Workshop on Monoxide Detec Basement (-Out asement, Lower Le blace, Forced Air-Pr ving Room, Wood ane Tank -in Microwave, Car her, Window Cover her "As Is", WiFi D 5 Chairs, Dock, All 's under Pergola	Lot Irregularities: Beach, Campground, Is, Shopping Nearby, ss/Woods, Water ng, Wooded/Treed I Fans, On Demand Wa ctor(s), Smoke Detec Basement Fin: vel ropane, In-Floor, Rad bon Monoxide Detec ings oor Lock, Living Rooi waterfront patio woo Plumbing Age: Tank Age:	Trails, Other Interior Inter Heater, Ventila Inter Heater, Ventila Inter Heater, Ventila Inter Heater, Ventila Inter Heater, Ventila Inter Heater Inter Heater In	Island, Marina, F Retire Com: Fronting On Exposure: ation System, Wa FP Stove Contract Dryer, Refrigeratu ights and Vine in irondak chairs, t Furnishe UFFI: Local Improvemen	Park, Place Park, Place Cost/Mo: Cost/Mo: or, Smoke Sunroom Naterfront d: ts Fee: vailable/	West r Owned, Water Yes Detector, Stove, , BBQ, Patio Tables

Source Board: Kingston and Area Real Estate Association Prepared By: Tammy Gurr, Broker Date Prepared: 10/23/2024

*Information deemed reliable but not guaranteed. * CoreLogic Matrix POWERED by <u>Itsorealestate.ca</u>. All rights reserved.



Questions? Contact us:


Tammy & Heath Gurr

Royal LePage ProAlliance Realty, Brokerage



Westport Office: 7 Spring Street, P.O. Box 148, Westport, ON K0G 1X0







ROYAL LEPAGE

NATIONAL TOP 1%

www.gurreathomes.com info@gurreathomes.com (613) 273-9595 Kingston Office: 640 Cataraqui Woods Drive Kingston, ON K7P 2Y5

Your Total Real Estate Package!