

INSPECTION DETAILS


TIME 12:30 P.M. DATE June 20, 2005 OWNER [REDACTED] INSTALLER Glen McNichols

1. Work has been satisfactorily completed and includes:

- Septic tank/holding tank of working capacity of (8006L) 3600 Litres constructed of steel ☐ concrete ☒ fiberglass ☐ plastic ☐ or prefabricated ☐ to serve 3 (no. of bedrooms, or units, commercial/business).
MAKE AND MODEL OF PREFABRICATED TANK Anchor Low
- Leaching/Filter Bed of total (32' 10") 3 metres of (4") 100 mm diameter distribution pipe of Carson's (type and product description) laid in 4 runs and fed by Gravity (gravity, siphon, pump). If Filter Bed, Leaching area (13' 03") 27.7 m² Contact Area m²
- Secondary or Tertiary Treatment: (Manufacturer) _____ (Model) _____
- Other details _____

2. Location

- System components installed as shown on application to install a Class 4,5 Sewage System ☐
- If located other than in (a) use space below for sketch and dimensions from permanent points of reference sufficient to facilitate future location of tank and leaching bed including orientation of pipe runs.



3. The following work remains to be completed:

- | | |
|---|--|
| ☒ Backfill System with suitable granular fill | ☐ Finish Grading to Shed Run-off and Divert Water Around Leaching Bed |
| ☐ Stabilize All Sloped Surfaces | ☐ Add Topsoil and Establish Grass Cover |
| ☐ Other _____ | |

The Sewage System was inspected and it has been determined that the installation complies with the requirements of Regulation 403/97 made under the

Building Code Act, for the following property located on Lot 11 Concession 3 Municipality S. Frontenac
District/Ward Bedford Municipal address _____ Plan No. 13R 284 Part(s) 405

Sub Lot No. _____
Inspector [Signature] Date June 27/05

2730258 ONTARIO LTD. o/a
BRYAN'S SEPTIC SERVICE
P.O. BOX 37
WESTPORT, ONTARIO
K0G 1X0

(613) 273-3078 Email: btcolford@hotmail.com

PUMPER REPORT
SEPTIC SYSTEM MAINTENANCE
& PUMPING INFORMATION

Name: [REDACTED]

Date: May 30 2025

Address: 21 Warbler Ln

Phone: _____

Location: White Lake Westport Rd

Type of Tank ☐ One Compartment ☒ Two Compartment

Type of Tank ☒ Septic Tank ☐ Graywater ☐ Aerobic ☐ Other _____

Approximate Capacity 800 gal

Construction Materials ☒ Concrete ☐ Steel ☐ Block ☐ Fiberglass ☐ Plastic
☐ Other _____

Initial Inspection

Any part of the septic tank under deck, driveway, etc ☐ Yes ☒ No

Any evidence of sewage seeping from the tank or lid ☐ Yes ☒ No

Condition of top and lids ☒ Good ☐ Leaking ☐ Needs Repair

Before Pumping

Condition of sewage in tank Normal

Liquid level at the outlet invert ☐ Above ☐ Below ☒ Normal

After Pumping

Condition of inlet baffle ☒ Good ☐ Needs Repair ☐ Missing

Condition of outlet baffle ☒ Good ☐ Needs Repair ☐ Missing ☐ Filter

Evidence of water leakage: Into Tank ☐ Yes ☒ No From Tank ☐ Yes ☒ No

Absorption System

Type of Absorption System ☐ Seepage Bed ☐ Sand Mound ☒ Sub-surface Sand Filter

Flow Test ☒ Yes ☐ No Approximate Seepage at Bed 30 min good

Comments

At time of pumping system in good
working condition

Bryan