

2730258 ONTARIO LTD. o/a
BRYAN'S SEPTIC SERVICE
P.O. BOX 37
WESTPORT, ONTARIO
K0G 1X0
(613) 273-3078 Email: btcolford@hotmail.com

PUMPER REPORT
SEPTIC SYSTEM MAINTENANCE
& PUMPING INFORMATION

Name: _____

Date: May 10-2022

Address: 30 Devereaux St

Phone: _____

Location: Nanticoke

Type of Tank ☐ One Compartment ☒ Two Compartment

Type of Tank ☒ Septic Tank ☐ Graywater ☐ Aerobic ☐ Other _____

Approximate Capacity 800 gal

Construction Materials ☒ Concrete ☐ Steel ☐ Block ☐ Fiberglass ☐ Plastic
☐ Other _____

Initial Inspection

Any part of the septic tank under deck, driveway, etc ☐ Yes ☒ No

Any evidence of sewage seeping from the tank or lid ☐ Yes ☒ No

Condition of top and lids ☒ Good ☐ Leaking ☐ Needs Repair

Before Pumping

Condition of sewage in tank Normal

Liquid level at the outlet invert ☐ Above ☐ Below ☒ Normal

After Pumping

Condition of inlet baffle ☒ Good ☐ Needs Repair ☐ Missing

Condition of outlet baffle ☒ Good ☐ Needs Repair ☐ Missing

Evidence of water leakage: Into Tank ☐ Yes ☒ No From Tank ☐ Yes ☒ No

Absorption System

Type of Absorption System ☒ Seepage Bed ☐ Sand Mound ☐ Sub-surface Sand Filter

Flow Test ☒ Yes ☐ No

Approximate Seepage at Bed 30 min good

Comments

At time of pumping system is working
cond it was

[Signature]