

2730258 ONTARIO LTD. o/a
BRYAN'S SEPTIC SERVICE
P.O. BOX 37
WESTPORT, ONTARIO
K0G 1X0

(613) 273-3078 Email: btcolford@hotmail.com

PUMPER REPORT
SEPTIC SYSTEM MAINTENANCE
& PUMPING INFORMATION

Name: Hewitt

Date: May 21 - 2025

Address: 37 C Chadwick Ln

Phone: _____

Location: Burn's Rd Bobs Lake

Type of Tank ☐ One Compartment ☒ Two Compartment

Type of Tank ☒ Septic Tank ☐ Graywater ☐ Aerobic ☐ Other _____

Approximate Capacity 800 gal

Construction Materials ☒ Concrete ☐ Steel ☐ Block ☐ Fiberglass ☐ Plastic

☐ Other _____

Initial Inspection

Any part of the septic tank under deck, driveway, etc ☐ Yes ☒ No

Any evidence of sewage seeping from the tank or lid ☐ Yes ☒ No

Condition of top and lids ☒ Good ☐ Leaking ☐ Needs Repair

Before Pumping

Condition of sewage in tank Normal

Liquid level at the outlet invert ☐ Above ☐ Below ☒ Normal

After Pumping

Condition of inlet baffle ☒ Good ☐ Needs Repair ☐ Missing

Condition of outlet baffle ☒ Good ☐ Needs Repair ☐ Missing ☒ Filter

Evidence of water leakage: Into Tank ☐ Yes ☒ No From Tank ☐ Yes ☒ No

Absorption System

Type of Absorption System ☐ Seepage Bed ☐ Sand Mound ☒ Sub-surface Sand Filter

Flow Test ☒ Yes ☐ No Approximate Seepage at Bed 30 min 2 good

Comments

At time of pumping system in good
working condition
clean filter yearly

By