

2730258 ONTARIO LTD. o/a  
BRYAN'S SEPTIC SERVICE  
P.O. BOX 37  
WESTPORT, ONTARIO  
K0G 1X0  
(613) 273-3078

PUMPER REPORT  
SEPTIC SYSTEM MAINTENANCE  
& PUMPING INFORMATION



rd@hotmail.com

Name: \_\_\_\_\_

Date: Aug 18 - 2023

Address: 350 Whiffenmill Ln

Phone: \_\_\_\_\_

Location: Massawega Rd Buck Lake

Type of Tank  One Compartment  Two Compartment  
Type of Tank  Septic Tank  Graywater  Aerobic  Other \_\_\_\_\_

Approximate Capacity 800 gal

Construction Materials  Concrete  Steel  Block  Fiberglass  Plastic  
 Other \_\_\_\_\_

**Initial Inspection**

Any part of the septic tank under deck, driveway, etc  Yes  No

Any evidence of sewage seeping from the tank or lid  Yes  No

Condition of top and lids  Good  Leaking  Needs Repair

**Before Pumping**

Condition of sewage in tank Normal

Liquid level at the outlet invert  Above  Below  Normal

**After Pumping**

Condition of inlet baffle  Good  Needs Repair  Missing

Condition of outlet baffle  Good  Needs Repair  Missing Has Filter

Evidence of water leakage: Into Tank  Yes  No From Tank  Yes  No

**Absorption System**

Type of Absorption System  Seepage Bed  Sand Mound  Sub-surface Sand Filter

Flow Test  Yes  No Approximate Seepage at Bed 30 min good

**Comments**

At time of pumping system in good working condition  
[Signature]