

2730258 ONTARIO LTD. o/a  
BRYAN'S SEPTIC SERVICE  
P.O. BOX 37  
WESTPORT, ONTARIO  
K0G 1X0

(613) 273-3078 Email: btcolford@hotmail.com

PUMPER REPORT  
SEPTIC SYSTEM MAINTENANCE  
& PUMPING INFORMATION

Name: [REDACTED]

Date: June 26, 2025

Address: Unit 7 Scarlett Ln

Phone: \_\_\_\_\_

Location: Lawrence Ln Cosby Lake

Type of Tank ☐ One Compartment ☒ Two Compartment

Type of Tank ☒ Septic Tank ☐ Graywater ☐ Aerobic ☐ Other \_\_\_\_\_

Approximate Capacity 800 gal

Construction Materials ☒ Concrete ☐ Steel ☐ Block ☐ Fiberglass ☐ Plastic  
☐ Other \_\_\_\_\_

Initial Inspection

Any part of the septic tank under deck, driveway, etc ☐ Yes ☒ No

Any evidence of sewage seeping from the tank or lid ☐ Yes ☒ No

Condition of top and lids ☒ Good ☐ Leaking ☐ Needs Repair

Before Pumping

Condition of sewage in tank Normal

Liquid level at the outlet invert ☐ Above ☐ Below ☒ Normal

After Pumping

Condition of inlet baffle ☒ Good ☐ Needs Repair ☐ Missing

Condition of outlet baffle ☒ Good ☐ Needs Repair ☐ Missing ☒ Filter

Evidence of water leakage: Into Tank ☐ Yes ☒ No From Tank ☐ Yes ☒ No

Absorption System

Type of Absorption System ☐ Seepage Bed ☐ Sand Mound ☒ Sub-surface Sand Filter

Flow Test ☒ Yes ☐ No Approximate Seepage at Bed 30 min good

Comments

At time of pumping system in good working  
condition  
Clean filter every few years

Bry