

21st May 2025

Rideau Valley Hearth and Home Ltd.
20 Whelan St., Box 239
Westport, Ontario
K0G 1X0
(613) 273-4402


To whom it may concern

In May, Rideau Valley Hearth and Home Limited installed ICC chimney parts to the existing chimney, which is attached to a code compliant Pacific Energy Vista, freestanding wood stove at 1679 Mountain Road, Westport, Ontario for the above customer.

At the time of installation, the installed system was to code.

If you have any questions or concerns, please do not hesitate to contact me at the telephone number above.

Yours Sincerely,



Mr. Jim Archambault
W.E.T.T. #3758

Sent by email 14/5/2025

Sweep Right Chimney Services

**Hearth
and Home**
Quality Hearth Products

Sweep Ri



Box 239, 20 Whelan St.
Westport Ont.
Tel. (613) 273-4402
1-888-743-3288
jima@rideau.net
www.rvvh.com

Customer: _____ Date: 14th May 2025

Address: 1679 Mountain Rd Westport T. _____ Bus. _____

Service Requested: Level 1 WETT Inspection

Manufacturer Pacific Energy Model Vista Fuel W Age _____

Rideau Valley Hearth & Home Customer Y N ☒ Lori Fryz UK@hotmail.ca

Appliance Type Free Standing Roof pitch 12/12

Chimney Type ICC Industrial Roof const. Asph

Date for Service _____ Time: Arrival _____ Departure _____

Checklist

Y N

RIDEAU VALLEY HEARTH & H
20 WHELAN STREET WESTPOR
WESTPORT, ON K0G1X0
6132734402

SALE PHONE ORDER

MID: 613455
TID: 0000
Bat: #134001 REF#: 00000001
05/11/25 RRN: 00000001
13:47:27
CVD: M

ORL: R#: 1794
APF: CODE: 018741
VIS: Manual CNP
**** 8655

AMOUNT \$282.50

APPROVED

MOIC X

I AGREE TO PAY ABOVE TOTAL AMOUNT
IN ACCORDANCE WITH CARD ISSUER'S
AGREEMENT
(MERCHANT AGREEMENT IF CREDIT VOUCHER)
RETAIN THIS COPY FOR STATEMENT
VERIFICATION

THANK YOU! / MERCI

Credit card, cash, or
e-transfer to: jima@rideau.net

WETT has no responsibility for
system areas that are not
WETT certified. Any system that is
not WETT certified is the
manufacturer's installation
Rideau Valley Hearth &
Home use by customer until
written deficiency letter is
& Home outlining work

Signature on completion.

Comments

Support box does not
extend far enough into
room.

Smoke pipe less than 6" clearance

System in wetter cooler
must not be used.

1- inspection 250
HST 3250
28250

PAID

Customer Signature

Technician Signature