

2730258 ONTARIO LTD. o/a
BRYAN'S SEPTIC SERVICE
P.O. BOX 37
WESTPORT, ONTARIO
K0G 1X0
(613) 273-3078 Email: btcolford@hotmail.com

PUMPER REPORT
SEPTIC SYSTEM MAINTENANCE
& PUMPING INFORMATION

Name: [REDACTED] Date: May 2 - 2026
Address: 311 Riverside Rd Phone: _____
Location: _____

Type of Tank One Compartment Two Compartment
Type of Tank Septic Tank Graywater Aerobic Other _____
Approximate Capacity 700 gal
Construction Materials Concrete Steel Block Fiberglass Plastic
 Other _____

Initial Inspection

Any part of the septic tank under deck, driveway, etc Yes No
Any evidence of sewage seeping from the tank of lid Yes No
Condition of top and lids Good Leaking Needs Repair

Before Pumping

Condition of sewage in tank Normal
Liquid level at the outlet invert Above Below Normal

After Pumping

Condition of inlet baffle Good Needs Repair Missing
Condition of outlet baffle Good Needs Repair Missing Filter
Evidence of water leakage: Into Tank Yes No From Tank Yes No

Absorption System

Type of Absorption System Seepage Bed Sand Mound Sub-surface Sand Filter

Flow Test Yes No Approximate Seepage at Bed 30 min good

Comments

setting of pumping system system in working condition
some decay in second chamber
[Signature]