

Sweep Right Chimney Services



Sweep Right! Sleep Tight!



Box 239, 20 Whelan St.
Westport Ont.
Tel. (613) 273-4402
1-888-743-3288
jima@rideau.net
www.rvhh.com

Customer: [Redacted] Date: 8th July 2026
Address: 1881B Massasauga Rd Tel: [Redacted]
South Frontenac Email: _____
Service Requested: Visual Inspection level 1
Manufacturer D-tul Model Castine Fuel W Age 22
Rideau Valley Hearth & Home Customer Y ☒ N _____
Appliance Type Hearth Stove
Chimney Type SS lined Masawry.

Checklist

	Y	N
Drop Sheets Used	☐	☐
Creosote Buildup	☐	☐
Gasket Checked	☐	☐
Glass Cleaned	☐	☐
Stove Painted	☐	☐
Brick Checked	☐	☐
Baffle Checked	☐	☐
Hinges Greased	☐	☐
Handle Adjusted	☐	☐
Air Tubes Vacuumed	☐	☐
Smoke Pipe Checked	☐	☐
Chimney Checked	☐	☐
Blower Cleaned	☐	☐

Rideau Valley Hearth & Home assumes no responsibility for the safety & code compliance of any system areas that are not clearly visible based on a visual inspection. Any system that is seen to be in violation of B-365 or manufacturers installation instructions can not be cleaned by Rideau Valley Hearth & Home and must be taken out of use by customer until appliance is brought up to code. A written deficiency letter is available from Rideau Valley Hearth & Home outlining work that must be done at a cost of \$95.00.

Payment is due immediately on completion.
Credit card, cheque, cash, or
e-transfer to: jima@rideau.net

Comments

Based on a Level #1
Visual inspection the
appliance & venting
appear in good visual
condition.

Jim Archambault
WETT #3758

1- inspection 299
AST 3828

Paid

33778

Customer Signature

Technician Signature