

Sweep Right Chimney Services



Sweep Right! Sleep Tight!



Box 239, 20 Whelan St.
Westport Ont.
Tel. (613) 273-4402
1-888-743-3288
jima@rideau.net
www.rvhh.com

Customer: XXXXXXXXXX Date: 31st Oct 2024

Address: 142 Kaddy's Lane Westport Tel: XXXXXXXXXX Bus: _____

Service Requested: Visual Inspection Level 1

Manufacturer Jotul Model 118 Fuel W Age 20

Rideau Valley Hearth & Home Customer Y ☒ N ☐

Appliance Type Free Standing Roof pitch _____

Chimney Type ICC Industrial Roof const. _____

Date for Service Oct 31 24 Time: Arrival _____ Departure _____

Checklist

	Y	N
Drop Sheets Used	☐	☐
Creosote Buildup	☐	☐
Gasket Checked	☐	☐
Glass Cleaned	☐	☐
Stove Painted	☐	☐
Brick Checked	☐	☐
Baffle Checked	☐	☐
Hinges Greased	☐	☐
Handle Adjusted	☐	☐
Air Tubes Vacuumed	☐	☐
Smoke Pipe Checked	☐	☐
Chimney Checked	☐	☐
Blower Cleaned	☐	☐

Rideau Valley Hearth & Home assumes no responsibility for the safety & code compliance of any system areas that are not clearly visible based on a visual inspection. Any system that is seen to be in violation of B-365 or manufacturers installation instructions can not be cleaned by Rideau Valley Hearth & Home and must be taken out of use by customer until appliance is brought up to code. A written deficiency letter is available from Rideau Valley Hearth & Home outlining work that must be done at a cost of \$95.00.

Payment is due immediately on completion.

Credit card, cheque, cash, or
e-transfer to: jima@rideau.net

Comments

Based on a Level #1 Visual
Inspection the appliance
& venting appear in good
visual condition.

Jim Archambault
WETT # 3758

1- inspection 250
HST 32.50

PAID 282.50

847.50

5191 2301 4581 9174 8/26 759

Customer Signature _____

Technician Signature _____

Sweep Right Chimney Services



Sweep Right! Sleep Tight!



Box 239, 20 Whelan St.
Westport Ont.
Tel. (613) 273-4402
1-888-743-3288
jima@rideau.net
www.rvhh.com

Customer: David Tigwell Date: 31st Oct 24
Address: 142 Paddys Lane Tel: 777-7810 Bus. _____
Service Requested: Level # Visual Inspection
Manufacturer Valmont Model FP7 Fuel W Age 20
Rideau Valley Hearth & Home Customer Y ☒ N ☐
Appliance Type Factory Built Fireplace Roof pitch _____
Chimney Type ICC Industrial Roof const. _____
Date for Service Oct 31st 24 Time: Arrival _____ Departure _____

Checklist

	Y	N
Drop Sheets Used	☐	☐
Creosote Buildup	☐	☐
Gasket Checked	☐	☐
Glass Cleaned	☐	☐
Stove Painted	☐	☐
Brick Checked	☐	☐
Baffle Checked	☐	☐
Hinges Greased	☐	☐
Handle Adjusted	☐	☐
Air Tubes Vacuumed	☐	☐
Smoke Pipe Checked	☐	☐
Chimney Checked	☐	☐
Blower Cleaned	☐	☐

Comments

Based on a level #1 Visual Inspection the appliance & venting appear in good visual condition.

Jim Archambault
WETT # 3758

Inspection 250.00
32.50
282.50

Paid

Rideau Valley Hearth & Home assumes no responsibility for the safety & code compliance of any system areas that are not clearly visible based on a visual inspection. Any system that is seen to be in violation of B-365 or manufacturers installation instructions can not be cleaned by Rideau Valley Hearth & Home and must be taken out of use by customer until appliance is brought up to code. A written deficiency letter is available from Rideau Valley Hearth & Home outlining work that must be done at a cost of \$95.00.

Payment is due immediately on completion.

Credit card, cheque, cash, or
e-transfer to: jima@rideau.net

Customer Signature

Technician Signature

Sweep Right Chimney Services



Sweep Right! Sleep Tight!



Box 239, 20 Whelan St.
Westport Ont.
Tel. (613) 273-4402
1-888-743-3288
jima@rideau.net
www.rvhh.com

Customer: [Redacted] Date: 31st Oct 24
Address: 142 Paddy's Lane Tel: [Redacted] Bus. [Redacted]
Service Requested: Level #1 Visual Inspection
Manufacturer Hampton Model H300 Fuel W Age 20
Rideau Valley Hearth & Home Customer Y ✓ N
Appliance Type Free Standing Roof pitch
Chimney Type ICC Industrial Roof const.
Date for Service Oct 31st 24 Time: Arrival Departure

Checklist

	Y	N
Drop Sheets Used	☐	☐
Creosote Buildup	☐	☐
Gasket Checked	☐	☐
Glass Cleaned	☐	☐
Stove Painted	☐	☐
Brick Checked	☐	☐
Baffle Checked	☐	☐
Hinges Greased	☐	☐
Handle Adjusted	☐	☐
Air Tubes Vacuumed	☐	☐
Smoke Pipe Checked	☐	☐
Chimney Checked	☐	☐
Blower Cleaned	☐	☐

Comments

Based on a Level #1 Visual inspection the appliance & venting appear in good overall condition.

Jim Archambault
WETT # 3758

1- inspection 250
HST 32.50
282.50

PAID

Rideau Valley Hearth & Home assumes no responsibility for the safety & code compliance of any system areas that are not clearly visible based on a visual inspection. Any system that is seen to be in violation of B-365 or manufacturers installation instructions can not be cleaned by Rideau Valley Hearth & Home and must be taken out of use by customer until appliance is brought up to code. A written deficiency letter is available from Rideau Valley Hearth & Home outlining work that must be done at a cost of \$95.00.

Payment is due immediately on completion.

Credit card, cheque, cash, or
e-transfer to: jima@rideau.net

Customer Signature

Technician Signature