



WETT RECOMMENDED INSPECTION CHECKLIST

Requested by: [REDACTED]	Inspection location: <input checked="" type="radio"/> Same as requested or:
Address: 2012 Shibley Rd Sharbot Lake, ON	Address:
Email:	Email:
Phone No: [REDACTED]	Phone No.:
Inspector's name: Ben Merkley	WETT No.: 12893
Reason(s) for inspection: Real Estate	
Level of inspection requested: <input checked="" type="radio"/> Level 1 <input type="radio"/> Level 2 <input type="radio"/> Level 3	
Date of request:	Date of inspection: November 19, 2024

Note: inspection results shown are what was present/noted at time of inspection.

This report documents findings at the time of the inspection. Compliance is referenced to currently published applicable codes and standards.



WETT RECOMMENDED INSPECTION CHECKLIST

FACTORY-BUILT CHIMNEY

Chimney Type: ULC S604 (Factory-built Type A) ULC S610 (Factory-built Fireplace Chimney)

ULC S629 (650°C) Uncertified Unknown

Listing Agency: ULC CSA WH/ETL OTL Other: _____

Make: Security **Model:** S2100

Installation manual available: Yes No

Installed by: _____ **Date:** _____ Unknown **Approx. Age:** 25 years

Installed in: Residence Mobile Home Garage
 Other: _____

Total height: 22' **Flue Size:** 7" Inside Installation Outside Installation

Connected to: fireplace **Make:** Heatilator **Model:** 2208 **Serial #:** AE 251135

Connected to: _____ **Make:** _____ **Model:** _____ **Serial #:** _____

Inspection Results: Indicate inspection results for each component. Code compliance includes proper use of listed components. N/A = Not Applicable UTI = Unable To Inspect.

All non-compliance ratings should be considered for comment.

An inspection at any level can be expected to include some components marked UTI.

COMPONENT	CODE COMPLIANCE			
1. Horizontal extension beyond inside wall surface	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
2. Wall radiation shield	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
3. Clean-out tee and cap	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
4. Wall supports	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
5. Ceiling support	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
6. Support spacing	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
7. Chimney offsets	<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI
8. Offset support	<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI
9. Firestopping	<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI

Factory-built Chimney - page 2

COMPONENT	CODE COMPLIANCE			
10. Attic radiation shield	<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI
11. Other radiation shield(s)	<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI
12. Enclosed through living space	<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
13. Roof flashing/storm collar	<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
14. Roof braces	<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
15. Rain cap	<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
16.	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
17. Height above roof surface	<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
18. Chimney clearance to combustibles	<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI
19.	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
20.	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
OTHER CONSIDERATIONS				
21. Areas of chimney enclosed or hidden	<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
22.				
23.				

Additional information:

Date: November 19, 2024

File Reference #: montgomeryfbchimney

File reference No.: montgomeryfbchimney

Photos taken: Yes No

This checklist contains 2 pages in total. This report contains 4 pages in total.


Comments and Observations:

All non-compliance ratings should be considered for comment.

System as a whole appears to meet or exceed code and manufacturers instructions

Document prepared by WETT Advisor and Inspector Melinda Hamill #8670

Please attach additional page(s) for this section.

<i>Customer Signature:</i>	<i>Inspector Signature:</i>  <i>Digital Signature:</i> #8670
<i>Date:</i>	<i>Date:</i> November 19, 2024



WETT RECOMMENDED INSPECTION CHECKLIST

Requested by: [REDACTED]	Inspection location: <input checked="" type="radio"/> Same as requested or:
Address: 2012 Shibley Rd Sharbot Lake, ON	Address:
Email:	Email:
Phone No: [REDACTED]	Phone No.:
Inspector's name: Ben Merkley	WETT No.: 12893
Reason(s) for inspection: Real Estate	
Level of inspection requested: <input checked="" type="radio"/> Level 1 <input type="radio"/> Level 2 <input type="radio"/> Level 3	
Date of request:	Date of inspection: November 19, 2024

Note: inspection results shown are what was present/noted at time of inspection.

This report documents findings at the time of the inspection. Compliance is referenced to currently published applicable codes and standards.



WETT RECOMMENDED INSPECTION CHECKLIST

FACTORY-BUILT FIREPLACE

Certification Standard:

ULC S610
 EPA
 UCSA B415
 Unknown
 Uncertified

Listing Agency:
 ULC
 CSA
 WH/ETL
 OTL
 Other: _____

Make: Heatilator **Model:** 2208

Serial #: AE 251135 **Flue Size:** 7"

Installation manual available:
 Yes
 No

Chimney system connected to fireplace: Yes

Is the chimney tested for use with this fireplace or listed in the installation manual?
 Yes
 No

ULC S604
 ULC S610
 ULC S629

Masonry
 Masonry with stainless steel liner
 Other: _____

Chimney: S610 **Make:** Security **Model:** S2100

System installed by: _____ **Date:** _____
 Unknown **Approx. Age:** 25 years

Appliance location:
 Basement
 Main Floor
 Other (specify): _____

Inspection Results: Indicate inspection results for each component. Code compliance includes proper use of listed components. N/A = Not Applicable UTI = Unable To Inspect.

All non-compliance ratings should be considered for comment.

An inspection at any level can be expected to include some components marked UTI.

FACE CLEARANCES	REQUIRED	ACTUAL(s)	CODE COMPLIANCE			
1. Combustible mantle shelf	UTI	35 1/2"	<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI
2. Combustible side legs	N/A	N/A	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
3. Combustible side trim	N/A	N/A	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
4. Combustible top trim	N/A	N/A	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
5. Non-combustible facing	N/A	N/A	<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
6. Combustible side wall	UTI	94"	<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI

Factory-built Fireplace - page 2

7. Hearth size	18"x48"	20"x61"	<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
8. Hearth material	Stone & Mortar	Stone & Mortar	<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
9. Hearth ember strip	UTI	UTI	<input type="radio"/> N/A	<input type="radio"/> No	<input type="radio"/> Yes	<input checked="" type="radio"/> UTI
10.						
11.						
OTHER CONSIDERATIONS		CODE COMPLIANCE				
12. Outdoor combustion air			<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
13. Remote gravity vent(s)			<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
14. Central heating kit			<input checked="" type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
15. Fireplace to chimney connection			<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
16. Is the fireplace enclosed?			<input checked="" type="radio"/> Yes <input type="radio"/> No			
17. Glass doors			<input type="radio"/> N/A	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
18. Clearances within enclosure			<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI
19. Ceiling height within enclosure			<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> UTI
20.			<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
21.			<input type="radio"/> N/A	<input type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> UTI
22. Carbon monoxide alarm			Yes			
23. Smoke alarm			Yes			

Additional information:

Date: November 19, 2024

File Reference #: montgomeryfbfireplace

File reference No.: montgomeryfbfireplace

Photos taken: Yes No

This checklist contains 2 pages in total. This report contains 4 pages in total.


Comments and Observations:

All non-compliance ratings should be considered for comment.

System as a whole appears to meet or exceed code and manufacturers instructions

Document prepared by WETT Advisor and Inspector Melinda Hamill #8670

Please attach additional page(s) for this section.

<i>Customer Signature:</i>	<i>Inspector Signature:</i>  <i>Digital Signature:</i> #8670
<i>Date:</i>	<i>Date:</i> November 19, 2024