



<p>Date of Inspection <b>July 2 2021.</b></p> <p>Customer </p> <p>Address <b>267 Pine Lane Maberly Ont.</b></p> <p>Inspection # <b>21070001W</b></p> <p>Inspector <b>Allan Taillefer</b></p> <p>WETT # <b>5887</b></p>	 <p><b>At Home Check Inc.</b> <b>613-267-8979</b></p>
---	---

## WOOD STOVE AND FLUE PIPE INSPECTION

Appliance Manufacturer	Pacific energy			Model	Spectrum	
Appliance Type	Space Heater			Date of Installation	Jun-05	
Certified	Yes					
CSA S627-M93	Yes					
ULC	1482-98	Yes	Serial number WH -	194286		

Appliance Clearances				Appliance Clearance Reduction		
	Required	Actual	Compliance	Wall Shield Type	Reduction %	Compliance
Left Side Corner	4"	11"+	Yes	Shield Extension	N/a	n/a
Right side Corner	4"	10"+	Yes	Sides & Back	N/a	n/a
Front	48"	48"+	Yes	Ceiling Shield		N/A
side wall to pipe	22.5"	23"	Yes			
Top	60"	>60"	Yes			
Mantel			N/A			
Comments				Comments		

Floor Pad Extension	Required	Actual	Compliance	Flue Pipe Type	double wall	Compliance
Sides and Rear	8"	25"	Yes	Diameter	6"	Yes
Front Loading	18"	20"	Yes	Gauge	24	Yes
Floor Pad	40"x48"	48"x72"	Yes	Length	60"	Yes
Material	Ceramic tile			Fasteners	N/a	Yes
Comments	As per installation spec.			Inspection Wrap		N/A
				Pipe Damper	N/a	N/A
				Condition	Good	Yes
				Orientation --	Male Down	Yes
				Rise Toward Chimney		Yes
				Properly Supported		Yes
				%Change of direction	0 degree	Yes

Chimney				Flue Pipe Clearance			
	Required	Actual	Compliance		Actual	Compliance	
Type	Factory built	S629	S629	Yes	Flue Pipe	6"	Yes
Chimney Clearance	2"	2"	Yes	Shielding Material	N/A	Yes	
Height above roof line	3'	3'	Yes	Shield Size	N/A	Yes	
Clearance above Roof	2'x10'	2'x10'	Yes	Clearance reduced to:	N/A	N/A	
Attic Shield	Metal	Metal	Yes	Chimney Breech	Metal	Yes	
ceiling support	Metal	Metal	Yes	Type	Metal	Yes	
Roof flashing	Metal	Metal	Yes	Condition	Good	Yes	
Roof bracing	N/A	N/A	Yes	Comments			
Rain cap	Installed	Installed	Yes				
overall condition	Good	Good	Yes				
Comments							

Chimney to be cleaned on a regular basis and burn dry clean wood. Clean at time of inspection.

This wood stove located in the living room appears to meet the Manufactures installation requirements.

At Home Check  
613-267-8979

---