

Address of Well Location (Street Number/Name) 42 Rebecca.		Township North Crosby	Lot 17	Concession 7
County/District/Municipality Leeds		City/Town/Village Westport.	Province Ontario	Postal Code _____
UTM Coordinates NAD 83	Zone 18	Easting 388243	Northing 4948979	Municipal Plan and Sublot Number _____

Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	To
black	earth			0	3.7
gray	clay			3.7	10.1
red	sandstone			10.1	24.4

Annular Space		
Depth Set at (m/ft) From 0	To 11.6	Type of Sealant Used (Material and Type) Cement
Volume Placed (m ³ /ft ³) 160 kg		

Method of Construction	Well Use
☐ Cable Tool ☒ Rotary (Conventional) ☐ Rotary (Reverse) ☐ Boring ☐ Air percussion ☐ Other, specify _____	☐ Diamond ☐ Jetting ☐ Driving ☐ Digging ☐ Public ☒ Domestic ☐ Livestock ☐ Irrigation ☐ Industrial ☐ Other, specify _____
☐ Commercial ☐ Municipal ☐ Test Hole ☐ Cooling & Air Conditioning ☐ Not used ☐ Dewatering ☐ Monitoring	

Construction Record - Casing				Status of Well
Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Well Thickness (cm/in)	Depth (m/ft) From To	☐ Water Supply ☐ Replacement Well ☐ Test Hole ☐ Recharge Well ☐ Dewatering Well ☐ Observation and/or Monitoring Hole ☐ Alteration (Construction) ☐ Abandoned, Insufficient Supply ☐ Abandoned, Poor Water Quality ☐ Abandoned, other, specify _____ ☐ Other, specify _____
15.85	steel	.188	0 11.6	

Construction Record - Screen				Status of Well
Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From To	☐ Water Supply ☐ Replacement Well ☐ Test Hole ☐ Recharge Well ☐ Dewatering Well ☐ Observation and/or Monitoring Hole ☐ Alteration (Construction) ☐ Abandoned, Insufficient Supply ☐ Abandoned, Poor Water Quality ☐ Abandoned, other, specify _____ ☐ Other, specify _____

Water Details		Hole Diameter	
Water found at Depth 14 (m/ft)	Kind of Water: ☒ Fresh ☐ Untested	Depth (m/ft) From To	Diameter (cm/in)
22 (m/ft)	Kind of Water: ☒ Fresh ☐ Untested	11.6 24.4	15.24
	Kind of Water: ☐ Fresh ☐ Untested		

Well Contractor and Well Technician Information			
Business Name of Well Contractor J R Thompson		Well Contractor's Licence No. 4905	
Business Address (Street Number/Name) 2076 Old Brooke Rd		Municipality Maberly	
Province ON	Postal Code K0H2B0	Business E-mail Address 	
Bus. Telephone No. (inc. area code) 6132674800		Name of Well Technician (Last Name, First Name) Darrell Stevenson	
Well Technician's Licence No. 2919		Signature of Technician and/or Contractor Brian Brady	
Date Submitted 20100605			

Results of Well Yield Testing					
After test of well yield, water was:		Draw Down		Recovery	
☐ Clear and sand free ☐ Other, specify _____		Time (min)	Water Level (m/ft)	Time (min)	Water Level (m/ft)
If pumping discontinued, give reason:		Static Level	2.5		
Pump intake set at (m/ft)		1	3	1	2.5
Pumping rate (l/min / GPM) 45		2	3.1	2	2.5
Duration of pumping 1 hrs + min		3	3.1	3	
Final water level end of pumping (m/ft) 3.1		4		4	
If flowing give rate (l/min / GPM)		5		5	
Recommended pump depth (m/ft) 22		10		10	
Recommended pump rate (l/min / GPM) 45		15		15	
Well production (l/min / GPM) 45		20		20	
Disinfected? ☒ Yes ☐ No		25		25	
		30		30	
		40		40	
		50		50	
		60	3.1	60	2.5

Map of Well Location	
Please provide a map below following instructions on the back.	

Well owner's information package delivered ☒ Yes ☐ No	Date Package Delivered 20100605	Ministry Use Only Audit No. z115751 SEP 15 2010
Date Work Completed 20100605		