



Ministry of
the Environment

Well Tag No. (Place Sticker and/or Print Below)

A085833

Well Record

Regulation 903 Ontario Water Resources Act

Measurements recorded in: ☒ Metric ☐ Imperial

Well Location

Address of Well Location (Street Number/Name) Hwy 42		Township North Crosby	Lot P1 7-8	Concession 6
County/District/Municipality Leeds County		City/Town/Village Westport	Province Ontario	Postal Code K0G 1X0
UTM Coordinates NAD 83	Zone 18	Easting 390726	Northings 4946363	Municipal Plan and Sublot Number

Overburden and Bedrock Materials/Abandonment Sealing Record (see instructions on the back of this form)

General Colour	Most Common Material	Other Materials	General Description	Depth (m/ft) From	To
Brown	Earth			0	1.2
Gray	Clay			1.2	7.6
Gray	Sandstone			7.6	18.3
White	Limestone			18.3	44.2
Red/Black	Granite			44.2	54.9

Annular Space		
Depth Set at (m/ft) From	To	Type of Sealant Used (Material and Type)
0	8.5	Cement

Method of Construction		Well Use		
☐ Cable Tool	☐ Diamond	☐ Public	☐ Commercial	☐ Not used
☒ Rotary (Conventional)	☐ Jetting	☒ Domestic	☐ Municipal	☐ Dewatering
☐ Rotary (Reverse)	☐ Driving	☐ Livestock	☐ Test Hole	☐ Monitoring
☐ Boring	☐ Digging	☐ Irrigation	☐ Cooling & Air Conditioning	
☐ Air percussion		☐ Industrial		
☐ Other, specify		☐ Other, specify		

Construction Record - Casing				Status of Well	
Inside Diameter (cm/in)	Open Hole OR Material (Galvanized, Fibreglass, Concrete, Plastic, Steel)	Wall Thickness (cm/in)	Depth (m/ft) From	To	
15.85	steel	.188	0	8.5	☒ Water Supply
					☐ Replacement Well
					☐ Test Hole
					☐ Recharge Well
					☐ Dewatering Well
					☐ Observation and/or Monitoring Hole
					☐ Alteration (Construction)
					☐ Abandoned, Insufficient Supply
					☐ Abandoned, Poor Water Quality
					☐ Abandoned, other, specify
					☐ Other, specify

Construction Record - Screen			
Outside Diameter (cm/in)	Material (Plastic, Galvanized, Steel)	Slot No.	Depth (m/ft) From
			To

Water Details		Hole Diameter	
Water found at Depth 13 (m/ft)	Kind of Water: ☒ Fresh ☐ Untested	Depth (m/ft) From	To
Water found at Depth 5.2 (m/ft)	Kind of Water: ☒ Fresh ☐ Untested	8.5	54.9
Water found at Depth (m/ft)	Kind of Water: ☐ Fresh ☐ Untested		

Business Name of Well Contractor J R Thompson		Well Contractor's Licence No. 4905
Business Address (Street Number/Name) 2076 Old Brooke Rd.		Municipality Maberly
Province ON	Postal Code K0H2B0	Business E-mail Address
Bus. Telephone No. (inc. area code) 613-267-4800	Name of Well Technician (Last Name, First Name) Darrell Stevenson	
Well Technician's Licence No. 2919	Signature of Technician and/or Contractor Briann Brady	
	Date Submitted 20090820	

Results of Well Yield Testing			
After test of well yield, water was: ☒ Clear and sand free ☐ Other, specify		Draw Down	
If pumping discontinued, give reason:		Time (min)	Water Level (m/ft)
Pump intake set at (m/ft) 52		Static Level	10.1
Pumping rate (l/min / GPM) 23		1	11.2
Duration of pumping 1 hrs + min		2	11.4
Final water level end of pumping (m/ft) 17.4		3	11.7
If flowing give rate (l/min / GPM)		4	11.9
Recommended pump depth (m/ft) 52		5	12.1
Recommended pump rate (l/min / GPM) 22		10	12.5
Well production (l/min / GPM) 21		15	13
Disinfected? ☒ Yes ☐ No		20	13.5
		25	14.0
		30	14.5
		40	15.6
		50	16.4
		60	17.4

Map of Well Location	
Please provide a map below following instructions on the back.	
Comments:	
Well owner's information package delivered ☒ Yes ☐ No	Date Package Delivered 20090820
Date Work Completed 20090920	
Ministry Use Only	
Audit No. 2103913	
SEP 24 2009	
Received	