

2730258 ONTARIO LTD. o/a  
BRYAN'S SEPTIC SERVICE  
P.O. BOX 37  
WESTPORT, ONTARIO  
K0G 1X0

(613) 273-3078 Email: btcolford@hotmail.com

PUMPER REPORT  
SEPTIC SYSTEM MAINTENANCE  
& PUMPING INFORMATION

Name: Laurel Barnes

Date: Sept 10 2025

Address: 98 Rocky Ridge

Phone: \_\_\_\_\_

Location: Crosby Lake

Type of Tank ☐ One Compartment ☒ Two Compartment

Type of Tank ☒ Septic Tank ☐ Graywater ☐ Aerobic ☐ Other \_\_\_\_\_

Approximate Capacity 800 gal

Construction Materials ☒ Concrete ☐ Steel ☐ Block ☐ Fiberglass ☐ Plastic  
☐ Other \_\_\_\_\_

Initial Inspection

Any part of the septic tank under deck, driveway, etc ☐ Yes ☒ No

Any evidence of sewage seeping from the tank or lid ☐ Yes ☒ No

Condition of top and lids ☒ Good ☐ Leaking ☐ Needs Repair

Before Pumping

Condition of sewage in tank 800 gal

Liquid level at the outlet invert ☐ Above ☐ Below ☒ Normal

After Pumping

Condition of inlet baffle ☒ Good ☐ Needs Repair ☐ Missing

Condition of outlet baffle ☒ Good ☐ Needs Repair ☐ Missing ☐ Filter

Evidence of water leakage: Into Tank ☐ Yes ☒ No From Tank ☐ Yes ☒ No

Absorption System

Type of Absorption System ☒ Seepage Bed ☐ Sand Mound ☐ Sub-surface Sand Filter

Flow Test ☒ Yes ☐ No Approximate Seepage at Bed 30 min good

Comments

at time of pumping system is working  
condition  
By



**HST #75775070**  
**Bryan Colford**  
**Septic Tank Pumping & Liquid Waste Disposal**  
P.O. Box 37, Westport, Ontario K0G 1X0  
**(613) 273-3078      Mobile (613) 264-3356**  
**e-Transfer payment with invoice # to:**  
**btcolford@hotmail.com**

45025

Product 609