

Sweep Right Chimney Services



Sweep Right! Sleep Tight!



Box 239, 20 Whelan St.
Westport Ont.
Tel. (613) 273-4402
1-888-743-3288
jima@rideau.net
www.rvhh.com

Customer: XXXXXXXXXX Date: 8th Jan 2025

Address: 211 McBride point Drive Westport Tel: XXXXXXXXXX Bus: _____

Service Requested: Visual Inspection level 1

Manufacturer Security Model B1S Fuel W Age 7

Rideau Valley Hearth & Home Customer Y ___ N

Appliance Type Factory Built Fireplace Roof pitch _____

Chimney Type Security Class A Roof const. _____

Date for Service 8 Jan 25 Time: Arrival _____ Departure _____

Checklist

	Y	N
Drop Sheets Used	<input type="checkbox"/>	<input type="checkbox"/>
Creosote Buildup	<input type="checkbox"/>	<input type="checkbox"/>
Gasket Checked	<input type="checkbox"/>	<input type="checkbox"/>
Glass Cleaned	<input type="checkbox"/>	<input type="checkbox"/>
Stove Painted	<input type="checkbox"/>	<input type="checkbox"/>
Brick Checked	<input type="checkbox"/>	<input type="checkbox"/>
Baffle Checked	<input type="checkbox"/>	<input type="checkbox"/>
Hinges Greased	<input type="checkbox"/>	<input type="checkbox"/>
Handle Adjusted	<input type="checkbox"/>	<input type="checkbox"/>
Air Tubes Vacuumed	<input type="checkbox"/>	<input type="checkbox"/>
Smoke Pipe Checked	<input type="checkbox"/>	<input type="checkbox"/>
Chimney Checked	<input type="checkbox"/>	<input type="checkbox"/>
Blower Cleaned	<input type="checkbox"/>	<input type="checkbox"/>

Rideau Valley Hearth & Home assumes no responsibility for the safety & code compliance of any system areas that are not clearly visible based on a visual inspection. Any system that is seen to be in violation of B-365 or manufacturers installation instructions can not be cleaned by Rideau Valley Hearth & Home and must be taken out of use by customer until appliance is brought up to code. A written deficiency letter is available from Rideau Valley Hearth & Home outlining work that must be done at a cost of \$95.00.

Payment is due immediately on completion.
Credit card, cheque, cash, or
e-transfer to: jima@rideau.net

Comments

Based on a Rvwf# / Visual Inspection the appliance & venting appear in good visual condition.

*Jim Archanbau IT
WETT # 3758*

*Inspection 250
HST 31⁰⁰
\$ 281⁰⁰*

PAID

Customer Signature _____

Technician Signature *[Signature]*